





Manufacturing Engineering 2

BAGGT23NEC

2013/14 I.

Dr. Mikó Balázs
miko.balazs@bgtk.uni-obuda.hu



Staff



Dr. Mikó Balázs
miko.balazs@bgk.uni-obuda.hu
Room 126



Szalóki István
szaloki.istvan@bgk.uni-obuda.hu
Room 137



Dr Zentay Péter
zentay.peter@bgk.uni-obuda.hu
Room 127

Schedule

- Week 1-6th - Cutting tools and methods
- Week 7-13th - Machine tools
- Week 14th - Test

- HomeWork 1 - Tool drawing
- HomeWork 2 - Operation planning
- HomeWork 3 -

Useful links


- <http://www.sandvik.coromant.com/en-gb/knowledge/pages/default.aspx>
- <http://www.kennametal.com/kennametal/en/resources/calculators.html>
- <http://mmu.ic.polyu.edu.hk/handout/0102/0102.htm>
- http://www.mitsubishicarbide.net/contents/mht/enuk/html/product/technical_information/index.html
- www.turning.fw.hu

01



BASICS OF CUTTING

Production process




Manufacturing methods

Forming	Cutting methods	Assembly
Sheet metal processing	Welding	Packaging
Moulding	Heat treatment	Testing and Measuring
Forging	Painting	



Manufacturing process







Fig. 1.2 (a) Typical accuracy and finish and (b) complexity and size achievable by machining, forming and casting processes, after Ashby (1992)





Advantages of cutting technology

- Good for piece production (cost, time)
- Accurate, good surface quality
- Good for every material
- Good for complex parts
- Homogenous material structure
- Easy to automate




Disadvantages of cutting technology

- High energy demand
- Waste material (chip)
- Different machine tools
- Lot of equipments
- CNC control
- Risk of accident
- Pollution (coolant liquid, chip, noise...)
- High cost



Cutting parameters (in case of turning)



n – Spindle speed [1/min]

v_c – Cutting speed [m/min]

$$n = \frac{1000 \cdot v_c}{D \cdot \Pi} \quad v_c = \frac{D \cdot \Pi \cdot n}{1000}$$

f – Feed [mm]

v_f – Feed speed [mm/min]

$$v_f = n \cdot f$$

a_p – Depth of cut [mm]

Material removal rate:

$$Q = a_p \cdot f \cdot v_c [\text{mm}^3 / \text{min}]$$

Primary motion


- **Ensures the cutting speed**
- Linear OR Rotational
- Continuous OR Periodical
- Done by the Tool OR by the Workpiece

Feed motion

- **Ensures the feed speed**
- Continuous OR Periodical (double stroke)
- Done by the Tool OR by the Workpiece


Cutting


- Hard tool – Tool materials
- Cutting edge – Edge geometry
- Relative motion – Cutting methods



Deformation zones

- Primary zone:
 - Shear of the material
 - Shearing force
- Secondary zone
 - Friction between the chip and the tool
- Tertiary zone
 - Friction between the tool and the part
 - Plastic deformation





1. Elastic deformation
2. Plastic deformation
3. Shearing
4. Welding of chip elements

SP – Shear plane

Φ – Shear plane angle

γ – Rake angle

h_1 – Undeformed chip thickness

h_2 – Deformed chip thickness

Chip contraction:

$$\lambda = \frac{h_2}{h_1}$$


Steels: 1.5 – 6

Cast iron: 1.5 – 2.5


$$h_1 \cdot v_c = h_2 \cdot v_{ch}$$

Chipformation

- Continuous chip
- Discontinuous segmented chip
 - C
- Broken chip
 - C
 - 6
 - Short spiral




Chipformation



- (1) continuous, long chipping, such as most steels
- (2) lamellar chipping, such as most stainless steels
- (3) short chipping, such as most cast-irons
- (4) varying, high force chipping, such as most super alloys
- (5) soft, low force chipping, such as aluminium
- (6) high pressure/temperature chipping, such as hard materials
- (7) segmental chipping, such as titanium

Turning test

a_p [mm]



(a)

	Feed (mm/rev)				
	0.05	0.053	0.08	0.1	0.14
DRY					
WET					
HTMF					


Cutting velocity=80m/min and depth of cut=1.25mm

(b)

	Cutting velocity (m/min)				
	40	53	80	91	120
DRY					
WET					
HTMF					

Feed = 0.1mm/rev and depth of cut=1.25mm

Chip breaking



Three ways to break a chip

A – Self breaking

Cutting conditions (v_c , f , a , *coolant*)

Tool geometry

Workpiece material (S, Pb)


B – Stopped by the tool

C – Stopped by the workpiece

Cutting tools' classification

- Cutting method: turning tool, drilling tool, milling cutter...
- Edge geometry: regular or unregular (statistical)
- Number of edges: 1, 2, many, much
- Edge shape: simple or shaped
- Build-up: solid (monolite), assembled (brazed, fixed by screw...)
- Edge material: steels, hard materials, super hard materials

Example



- Turning tool
- Regular edge geometry
- Number of edges: 1
- Simple edge
- Assembled built-up
- Hard material (sintered carbide)

Example



- Milling cutter
- Regular edge geometry
- Number of edges: 10
- Shaped edge
- Solid built-up
- Steel material (HSS)


Example



- Grinding tool
- Unregular edge geometry
- Number of edges: infinity
- Simple edge
- Solid built-up
- Composite




Parts of a cutting tool



Parts of a cutting tool

Edge zone




Tool shank


Parts of a cutting tool

Edge zone


Tool shank



Edge geometry



Edge geometry



Edge geometry

κ_r – Cutting edge angle

ε_r – Nose angle

κ'_r – Minor cutting edge angle


α_o – Flank angle

β_o – Wedge angle

γ_o – Rake angle

r_ε – Nose radius

*Perpendicular
to the edge*



$$\alpha_o + \beta_o + \gamma_o = 90$$

$$\kappa_r + \varepsilon_r + \kappa'_r = 180$$

Definitions

Shank – It is main body of tool. The shank used to be gripped in tool holder.

Flank – The surface or surface below the adjacent of the cutting edge is called flank of the tool.

Face – It is top surface of the tool along which the chips slides.

Base – It is actually a bearing surface of the tool when it is held in tool holder or clamped directly in a tool post.

Heel – It is the intersection of the flank and base of the tool. It is curved portion at the bottom of the tool.


Nose – It is the point where side cutting edge & base cutting edge intersect.

Cutting edge – It is the edge on face of the tool which removes the material from workpiece. The cutting edges are side cutting edge (major cutting edge) & end cutting edge (minor cutting edge)

Tool angles - Tool angles have great importance. The tool with proper angle, reduce breaking of tool, cut metal more efficiently, generate less heat.

Nose radius – It provide long life and good surface finish sharp point on nose is highly stressed, and leaves grooves in the path of cut. Longer nose radius produce chatter.

Tool materials





Requirements


- Hardness
- Wear resistance
- Strength
- Toughness
- Heat resistance

Steel materials


- Unalloyed tool steels
 - Fe + C; Hardening 66-67 HRc
- Alloyed tool steel
 - Mn (manganese), 60-62 HRc
 - W (tungsten), 62-64 HRc
 - Cr (chromium); 62-64 HRc
 - High speed steel (HSS) (W, Cr, V, Mo, Co); 63-70 HRc

Hard materials

- Cemented tungsten carbide
 - Powder production – Forming – Sintering (heat treatment) - Coating
 - Composite material: Co + WC, TiC
 - 87-92 HRA




Coated
cemented carbide




Uncoated
cemented carbide

Hard materials

- Ceramic
 - Al_2O_3 / $\text{Al}_2\text{O}_3 + \text{TiC}$ / Si_3N_4
 - 90-96 HRA
 - Rigid but high heat resistance (1400°C)




Pure-ceramic



Mixed ceramic

- CerMet – Ceramic metal
 - Mo, Ni + TiC, TiN, TiCN




Cermet

Super hard material


- Diamond
 - Not for steels!!!

Polycrystalline
diamond



- CBN – Cubic boron nitride
 - For hardened steel (65 HRc)

Cubic boron
nitride






Coating technology

- Aim:
 - Increase the wear and heat resistance
 - Decrease the friction coefficient and heat
- Technologies:
 - CVD
 - PVD
- Thickness: 2-12 μm


CVD – Chemical vapour deposition

- Multi-layer coating
- Chemical reaction of gases




Chemical vapour deposition

Multi layer coating




PVD – Physical vapour deposition



- Environment friendly
- Not so expensive
- Flexible




Physical vapour deposition

History






Summary



Increasing productivity



Production of components per cutting edge changed considerably, with that of HSS to cemented carbide

Increasing cutting parameters

