





# Manufacturing Engineering 2

## BAGGT23NEC

2013/14 I.


Dr. Mikó Balázs  
[miko.balazs@bgtk.uni-obuda.hu](mailto:miko.balazs@bgtk.uni-obuda.hu)



03




# CUTTING METHODS

- 
- Turning
  - Milling
  - Drilling
  - Reaming

- Grinding
- Planning
- Shaping
- Broaching

# Turning



Primary motion:  
continuous  
rotating  
workpiece

Feed motion:  
continuous  
tool

$$v_c \Rightarrow \textit{known}$$

$$n = \frac{1000 \cdot v_c}{D \cdot \Pi}$$

$$f \Rightarrow \textit{known}$$

or

$$f \Rightarrow R_t = 4 \cdot R_a = \frac{f^2}{8 \cdot r_\epsilon}$$

$$f = \sqrt{4 \cdot R_a \cdot 8 \cdot r_\epsilon}$$

$$v_f = n \cdot f$$

$$t_c = \frac{L}{v_f} = \frac{L_{pre} + L_c + L_{post}}{v_f}$$

Ra: 0.8 – 6.3  $\mu\text{m}$


IT: (7) 8 - 12



# Operation steps


- 1) Turning
- 2) Facing
- 3) Grooving
- 4) Face grooving
- 5) Parting
- 6) Thread turning
- 7) Boring

# Turning



Feed is parallel with the axis.


# Facing



Feed is perpendicular to the axis.  
D is changed continuously.

$$v_{c\_facing} = v_{c\_turning}$$

# Grooving




Feed is perpendicular to the axis.  
 $D$  is changed continuously.

$$v_{c\_grooving} = v_{c\_turning}$$





# Parting




Feed is perpendicular to the axis.

$D$  is changed continuously.


$$v_{c\_parting} = (0.2 \dots 0.5) v_{c\_turning}$$

# Thread turning




Feed is parallel with the axis.  
Feed is equal to pitch.

$v_{c\_parting} = (0.4 \dots 0.5) v_{c\_turning}$   
But the  $v_f$  means constrain.



# Boring


n



Feed is parallel with the axis.


$$v_{c\_parting} = (0.7 \dots 1.0) v_{c\_turning}$$





<http://turning.fw.hu>

# Milling




Copyright © 2007 CustomPartNet

Primary motion:  
continuous  
rotating  
tool

Feed motion:  
continuous  
tool / workpiece

Ra: 0.8 – 6.3  $\mu\text{m}$

IT: 9 - 12



$v_c \Rightarrow \text{known}$

$$n = \frac{1000 \cdot v_c}{D \cdot \Pi}$$


$f_z \Rightarrow \text{known}$

$$f = f_z \cdot z$$

$$v_f = n \cdot f$$

$$t_c = \frac{L}{v_f} = \frac{L_{pre} + L_c + L_{post}}{v_f}$$

# Cutting forces – plain milling



Average chip thickness:

$$\bar{h} = f_z \cdot \sqrt{\frac{a_e}{d}} \quad [\text{mm}]$$

Chip cross section:


$$\bar{A}_1 = \bar{h} \cdot a_p = \sqrt{\frac{a_e}{d}} \cdot f_z \cdot a_p \quad [\text{mm}^2]$$

Average cutting force:

$$\bar{F}_c = \bar{k} \cdot a_e \cdot a_p \cdot f_z \cdot \frac{z}{d \cdot \pi} \quad [\text{N}]$$


$$\bar{k} = \frac{k_{c1.1}}{\bar{h}^{q_c}} \quad [\text{N}]$$

*As a general rule - use down milling tool paths.*



### Down milling

- Less heat generation.
- Compressive stresses favourable for the carbide edge.
- Longer tool life.
- Better surface finish.
- Better geometrical accuracy.
- More friendly to spindle bearings.





### Up milling

- Better wall straightness and more accurate corner angle when side milling – finishing.
- Little or no mismatch between subsequent toolpaths.
- Makes somewhat worn manual machine tools perform better.



# Cutting forces – face milling



Average cutting force:



$$\bar{F}_c = \bar{k} \cdot a_e \cdot a_p \cdot f_z \cdot \frac{z}{d \cdot \pi} \quad [\text{N}]$$

Cutting torque:

$$M_c = \frac{\bar{F}_c \cdot d}{2000} \quad [\text{Nm}]$$


Cutting power:

$$P_c = \frac{M_c \cdot n}{9550} \quad [\text{kW}]$$





# Operation steps

1. Plane or face milling
2. Shoulder milling
3. Shoulder milling
4. Groove or keyway milling
5. Edge milling
6. Pocket milling
7. Contour milling
8. Slot milling and cut off
9. Chamfer milling




# 1. Plane or face milling




Lead angle < 90°

## 2. Shoulder milling with face mill





Lead angle = 90°

Short edge  
Small  $a_p$   
Large  $a_e$





### 3. Shoulder milling with end mill




Long edge  
 Large  $a_p$   
 Small  $a_e$

#### 4. Groove or keyway / keyseat milling





## 5. Edge milling





## 6. Pocket milling



## 7. Contour milling












Bild 5.3: Fräsoptionen nutzen im Werkzeug- und Formenbau einen wesentlichen Stellenwert ein.




## 8. Slot milling and cut off



## 9. Chamfering




# Drilling



Copyright © 2007 CustomPartNet

Ra: 3.2 – 25  $\mu\text{m}$   
IT: 10 – 12  
Max. diameter: 25 mm



Primary motion:  
continuous  
rotating  
tool

Feed motion:  
continuous  
tool

$v_c \Rightarrow \text{known}$

$$n = \frac{1000 \cdot v_c}{D \cdot \Pi}$$


$f_z \Rightarrow \text{known}$

$$f = f_z \cdot z$$

$$v_f = n \cdot f$$

$$t_c = \frac{L}{v_f} = \frac{L_{pre} + L_c (+ L_{post})}{v_f}$$



$\sigma$ :      118 - Steels  
             130 - High alloyed steels  
             130 - Aluminium



$$h = \frac{f}{2} \cdot \sin \frac{\sigma}{2} \quad [\text{mm}]$$

$$b = \frac{d}{2 \cdot \sin \frac{\sigma}{2}} \quad [\text{mm}]$$

# Twist drill



# Cutting force

Cutting force in one edge:

$$F_{c1} = \bar{k} \cdot A = \bar{k} \cdot h \cdot b = \bar{k} \cdot \frac{f \cdot d}{4} = \frac{k_{c1.1}}{h^{q_c}} \cdot \frac{f \cdot d}{4} \quad [\text{N}]$$

Cutting force:

$$F_c = 2 \cdot F_{c1} = k \cdot \frac{f \cdot d}{2} = \frac{k_{c1.1}}{h^{q_c}} \cdot \frac{f \cdot d}{2} \quad [\text{N}]$$

$$F_c = \frac{k_{c1.1}}{(0,5 \cdot \sin \sigma / 2)^{q_c}} \cdot \frac{f^{1-q_c} \cdot d}{2} \quad [\text{N}]$$

Cutting torque:

$$M_c = F_{c1} \cdot \frac{d}{2} = \frac{k \cdot f \cdot d^2}{4 \cdot 2 \cdot 1000} \quad [\text{Nm}]$$


$$M_c = \frac{k_{c1.1}}{(0,5 \cdot \sin \sigma / 2)^{q_c}} \cdot \frac{f^{1-q_c} \cdot d^2}{8000} \quad [\text{Nm}]$$

Cutting power:

$$P_c = \frac{M_c \cdot n}{9550} \quad [\text{kW}]$$




# Hole making operations




**FIGURE 8.7:** Related drilling operations: (a) reaming, (b) tapping, (c) counterboring, (d) countersinking, (e) centering, (f) spotfacing.

# Reaming



Ra: 0.2 – 1.6  $\mu\text{m}$   
IT: 6 – 7  
Max. diameter: 30 mm



Primary motion:  
continuous  
rotating  
tool

Feed motion:  
continuous  
tool



HSS reamer with taper shank





HSS TiN coated reamer with taper shank



HM TiN coated assembled reamer with cylindrical shank


# Surface grinding





Primary motion:  
continuous  
rotating  
tool

Feed motion:  
periodical  
tool or workpiece

Ra: 0.1 – 0.8  $\mu\text{m}$   
IT: 3 - 6





Horizontal spindle reciprocating table




Horizontal spindle rotary table




Vertical spindle rotary table



Vertical spindle reciprocating table




Horizontal spindle reciprocating table




Through feed type



Carrier type





Traverse grinding




Plunge grinding




Angular slide grinding



Through feed grinding




Infeed grinding




Standard type



Planetary type  
(revolving grinding wheel axis)



Centerless shoe type




Centerless roller type



Tool grinding


Turning tool, Drill, Milling, Hob, Broach, Pinion cutter, End mill




Turning tool grinding




Drill grinding



Milling cutter grinding



Hob grinding



Broach grinding



End mill grinding

# Machinery parts & other grinding



Roll grinding



Crankshaft grinding



Camshaft grinding


Roll grinding

Crank grinding


Cam grinding

Gear grinding

Thread grinding




Gear grinding



Thread grinding

# Planing



Primary motion:  
periodical  
linear  
tool OR workpiece


Feed motion:  
periaodical  
workpiece

Ra: 0.8 – 3.6  $\mu\text{m}$

IT: 9 - 12

(Turning,  $D = \infty$ )

# Shaping





Primary motion:  
periodical  
linear  
tool

Feed motion:  
periaodical  
tool

Ra: 0.8 – 3.6  $\mu\text{m}$   
IT: 9 - 12


# Broaching




Primary motion:  
continuous  
linear  
tool

Feed motion:  
„periodical”  
tool

Ra: 0.2 – 0.8  $\mu\text{m}$   
IT: 7 - 9





	Primary motion			Feed motion	
Turning	Rot	Cont	WP	Cont	Tool
Milling	Rot	Cont	Tool	Cont	Tool/WP
Drilling	Rot	Cont	Tool	Cont	Tool/WP
Reaming	Rot	Cont	Tool	Cont	Tool/WP
Grinding - Plane	Rot	Cont	Tool	Per	WP
Grinding - Cylindrical	Rot	Cont	Tool	Cont/Per	Tool/WP
Planing	Lin	Per	Tool	Per	Tool
Shaping	Lin	Per	Tool	Per	Tool
Broaching	Lin	Cont	Tool		