




Forgácsolástechnológia számítógépes tervezése I. házi feladat alkatrészek
A rajz melletti sorszám azonosítja az alkatrészt




E-1.




E-2.




E-3.




E-4.




E-5.




E-6.




E-7.




E-8.




E-9.




E-10.




E-11.




E-12.




E-13.




E-14.




E-15.




E-16.




E-17.




E-18.




E-19.



E-20.




E-21.




E-22.






E-25.




E-26.







E-29.



E-30.




E-31.




E-32.









E-37.




E-38.




E-39.



E-40.




E-41.




E-42.







E-45.




E-46.




E-47.




E-48.




E-49.




E-50.




E-51.




E-52.




E-53.




E-54.




E-55.




E-56.




E-57.




E-58.




E-59.




E-60.




E-61.




E-62.




E-63.




E-64.




E-65.




E-66.




E-67.




E-68.




E-69.




E-70.




E-71.




E-72.




E-73.




E-74.




E-75.




E-76.




E-77.




E-78.




E-79.




E-80.



E-81.



E-82.



E-83.